

# **Cost-effective Rollover Protective Structure (CROPS)**

for Wheeled Agricultural Tractors

Massey Ferguson 135 SERIES

FIELD INSTALLATION PHOTOS

Note: “Left” and “Right” refer to the tractor operators’ left or right as they sit in the seat looking forward.

---

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
Centers for Disease Control and Prevention  
National Institute for Occupational Safety and Health



**This document is in the public domain and may be freely copied or reprinted.**

## **Disclaimer**

Mention of any company or product does not constitute endorsement by the National Institute for Occupational Safety and Health (NIOSH). In addition, citations to Web sites external to NIOSH do not constitute NIOSH endorsement of the sponsoring organizations or their programs or products. Furthermore, NIOSH is not responsible for the content of these Web sites. All Web addresses referenced in this document were accessible as of the publication date.

## **Ordering Information**

To receive documents or other information about occupational safety and health topics, contact NIOSH at

Telephone: 1-800-CDC-INFO (1-800-232-4636)

TTY: 1-888-232-6348

E-mail: [cdcinfo@cdc.gov](mailto:cdcinfo@cdc.gov)

or visit the NIOSH Web site at [www.cdc.gov/niosh](http://www.cdc.gov/niosh).

For a monthly update on news at NIOSH, subscribe to NIOSH eNews by visiting [www.cdc.gov/niosh/eNews](http://www.cdc.gov/niosh/eNews).

**SAFER • HEALTHIER • PEOPLE™**

# Completed Massey Ferguson 135 CROPS Installations



*CROPS Field Installation Photos, Massey Ferguson 135 Series*

**Before**



**After**



**Before**



**After**



**Before**



**After**



*CROPS Field Installation Photos, Massey Ferguson 135 Series*  
Field Photos of Massey Ferguson 135 CROPS



Step 1 Close Up



Step 3 Close Up



Steps 1-3 Installation of Parts 1-4 and Fenders



Steps 5-7 Installation of  
Left Vertical Tube Part 6L



Steps 11-13 Installation of  
Right Vertical Tube Part 6R



Steps 14-16 Rear View

*CROPS Field Installation Photos, Massey Ferguson 135 Series*  
Field Photos of Massey Ferguson 135 CROPS



Steps 17-19 Installing Cross Bar Rear View



Steps 20-23 Proper Bolt Torque



Steps 20-23 Proper Bolt Torque



Final Step Install Plastic End Caps





**Delivering on the Nation's promise:  
Safety and health at work for all people  
through research and prevention**

To receive documents or other information about occupational safety and health topics, contact NIOSH at

Telephone: 1-800-CDC-INFO (1-800-232-4636)

TTY: 1-888-232-6348

E-mail: [cdcinfo@cdc.gov](mailto:cdcinfo@cdc.gov)

or visit the NIOSH Web site at [www.cdc.gov/niosh](http://www.cdc.gov/niosh).

For a monthly update on news at NIOSH, subscribe to NIOSH eNews by visiting [www.cdc.gov/niosh/eNews](http://www.cdc.gov/niosh/eNews).

**SAFER • HEALTHIER • PEOPLE™**